CENTRAL INTELLIGENCE AGENCY

INFORMATION REPORT

This Document contains information affecting the National Defense of the United States, within the meaning of Title 18, Sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law. The reproduction of this form is prohibited.

				, , , , , , , , , , , , , , , , , , , ,	JS OFFICIAI	D ONE		619410	25 X 1
COUNTRY		USSR ((Black Sea)			REPORT			
SUBJECT		Port of	f Odessa			DATE DISTR.		9 July 1954	
						NO. OF PA	GES	2	
ATE OF I	NFO.					REQUIREMENT	r NC		
LACE ACG	QUIRED					REFERENCES			25 X 1
									05)(4
**		This is	s UNEVALUAT	ΓED Inform	ation				25X1
			THE SOURCE EV THE AF	PPRAISAL OF CO	THIS REPORT A ONTENT IS TEN EE REVERSE)				25X1
1. [pilot			ship	was anchor	ed in the Od	iessa road	s_awaiting_the	25X
2.	ship berthed at the southeast side of the coal pier, (also called the new pier, near the shore end of the pier. The coal pier was in good operating condition. Loading was speedily accomplished by a large number of jib cranes, each of which had a capacity of between four and six tons.								
3.	A 100-ton floating pontoon crane was moored at the quay between the coal pier and the Platonovskiy pier.								*
4.	There	were no	vessels unde	er repair	in the por	t.			05V4
5 .	The fo	ollowing	ships were i	in the por	t:				25X1
	a. /	ln 8,000	-ton Soviet son coal.	_		d			, Tr
									25X1 -
	٤	stern fi	15,000-ton Sorst at the heat the souther	arbor side	of the qu	arantine mol	nich was m	oored ther vessel	
	d. I	'wo sail orthern	ing vessels v side of the	vith auxil Platonovs	iary motor kiy pier.	s, which were	moored a	t the	
	e. V	arious	small craft i	in the qua	rantine ha	rbor.			
			Q TO D TO	r /CONTROL	US OFFICIA	TO ONLY			
			CECTIFIE	7001111011-	OD OLLTOIN	ro OMTI			

-	SECRET/CONTROL-US OFFICIALS ONLY	25 X 1
	-2-	
	f. The naval training ship DUNAY, which was moored at the head of the coal pier. No other naval vessels were in the port.	
,	The large square in front of the customs office was being used as a storage lot for a large number of new automobiles Presumably these vehicles were awaiting shipment out of port to the square there were also many large crates which contained machinery.	25X1
·.	A radio station and a port signal station were located on the outer mole in the southeast part of the port. No aircraft were observed in flight.	25X1
·.	In operation along the coast, one located at approximately N 46-27-30, E 30-45-30, and the other at approximately N 46-33-00, E 30-49-20.	
		25 X 1
		•

SECRET/CONTROL-US OFFICIALS ONLY